

## Installation Instructions


900353-01 – PIM Cable Support Bar, Pole Mount Kit, 22 Position

900353-02 – PIM Cable Support Bar, Pole Mount Kit, 22 Position, Extended Range

### STEP 1

Attach threaded rods to bracket, set to correct offset length. (Torque greater than 20 Ft-lb)


### STEP 1



### STEP 2

Attach saddle brackets to pole.


### STEP 2



### STEP 3

Attach 22 Position Bar to threaded rods.

### STEP 3



Torque: 20 Ft-lb all connections  
 (ConcealFab Tool PN: 900413)

## Installation Instructions


900353-01 – PIM Cable Support Bar, Pole Mount Kit, 22 Position

900353-02 – PIM Cable Support Bar, Pole Mount Kit, 22 Position, Extended Range

### STEP 1

Attach threaded rods to bracket, set to correct offset length. (Torque greater than 20 Ft-lb)


### STEP 1



### STEP 2

Attach saddle brackets to pole.


### STEP 2



### STEP 3

Attach 22 Position Bar to threaded rods.

### STEP 3



Torque: 20 Ft-lb all connections  
 (ConcealFab Tool PN: 900413)